

Fig. 1






Fig. 2






Fig. 3d




Fig. 4

5/9




Fig. 5a




Fig. 5b

6/9




Fig. 6a




Fig. 6b





Fig. 7





Recommendations:

Check cabling on node 10.1.10.2, port 1 of slot 4 and port 1 of slot 5

Fig. 8

